

**Subject:** 8 HD Lid Stop with Thumb Rest Service Pack

**Date:** 02/14/22


**Regions Affected:** Global

**Models Affected:** 8-HD fryers, models: OFE 290, 291, 292; OFG 390, 391, 392; PFE 580, 581, 590, 591, 592; PFG 690, 691, 692

### Summary

Lid stop with thumb rest service pack 183138 is now available for 8-head fryers models, listed above. This optional service pack provides the addition of a bolt (thumb rest) that is used as a handle to assist with tilting and lowering the lid from the cleaning position. The addition of this thumb rest will also be implemented on all production units.

**WARNING!** Do not perform the lid stop replacement procedure with the lid tilted up for cleaning. Failure to do so may cause personal injury. Images below represent lid up for cleaning with lid stop engaged.



### Part Numbers

The lid stop service pack includes the following parts.

Part #	Description	Qty.
183138	Lid Stop Service Pack	1
	- Retaining Ring (e-clip)	1
	- Flat Washer	1

### Customer Training:

<https://vimeo.com/635502643/9d18b45d7c>

### Questions

For further information, please contact Technical Services using one of the following options:

Email: [technicalservices@hennypenny.com](mailto:technicalservices@hennypenny.com)

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405  
Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.

### Warranty

The service pack includes a 90-day parts warranty from the date of install.