

Subject: High Limit Part Number 60241 - Temporary Deviation

Date: 01/25/22

Region: Global

Models Affected: 320 and 340 Series open fryers

Summary

Due to global supply shortages a limited number of 320 and 340 Series open fryers may be built with high limit part number (P/N) 60241, which will have a longer capillary tube.



Deviation

The normal specification for high limit P/N 60241 is a 24 in. capillary tube. The temporary high limit deviation will allow for a 48 in. capillary tube.

- This deviation will prevent potential delays in manufacturing 320 and 340 series open fryers.
- The longer high limit capillary tube will not affect fryer performance in any way.
- Servicers will notice the additional capillary tube length coiled as needed.

Service Part Orders

Service parts for high limit P/N 60241 are not affected by the temporary deviation. All service part orders for high limit P/N 60241 will include the standard 24 in. capillary tube length.

Warranty

Parts includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.