

Subject: Updated fan wheel for FlexFusion and SpaceSaver Combi

Date: 02/01/22

Region: Global

Models Affected: FlexFusion SpaceSaver Gen2 (FSEN, FSHN) and SpaceSaver Team (FSD, FSDH)

Summary

Updated fan wheel for FlexFusion SpaceSaver Gen2 (FSEN, FSHN) and SpaceSaver Team (FSD, FSDH).

What's changed

Starting with serial number (S/N) 21536705 (from July 2021) the cabinet fan wheel was changed. The new fan wheel design provides a higher oven vent air flow than before. Increased oven air flow reduces vent hose temperatures and provides better performance during the WaveClean drying step.

Part number

The updated fan wheel part number (P/N) MM10029463 replaces the previous fan wheel P/N MM10018528.

- P/N **MM10018528** is no longer available and is obsolete.
- If you have P/N **MM10018528** in stock, please send a picture of the part(s) to RMAReturns@hennypenny.com to receive a credit for the part(s). Once you receive credit, scrap the part(s).
- Replace with:

Model	Part #	Description	Stocking Level	Qty.
FSEN, FSHN, FSD, FSDH	MM10029463	Fan Wheel, 200 mm dia., 43 mm deep		1

Warranty

This part includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.