

Subject: LVE 10X Drain Valve Actuator Service Pack

Date: 01/26/23

Region: Global

Model Effected: LVE 100 Fryers

Summary

As part of continuous improvement HP has redesigned the LVE 100 drain valve actuator. The individual actuator P/N 76783 for LVE 10X is now obsolete. Drain valve actuator service pack P/N 182853 replaces P/N 76783.

Part Numbers

Service providers may continue to use existing inventory of P/N 76783 for LVE 10X until depleted. Once stock is depleted order the following stock.

| Model | Part # | Description | Stocking Level | Quantity |
|-------|--------|-----------------------------------|----------------|-------------|
| LVE | 182853 | Drain Valve Actuator Service Pack | As required | As required |

Warranty

The kit includes a 90-day parts warranty from the date of install.

Questions

For further information, please contact Technical Services using one of the following options:

Email: technicalservices@hennypenny.com

Call:

- U.S. and Canada: +1-800-417-8405
- Global: +1-937-456-8405

Text: +1-937-456-8405

[Live chat](#) via the Henny Penny website, extranet, or customer support website.

Try our Henny Penny Service YouTube Channel: www.youtube.com/hennypennyservice.